


Object name

Client:
Location:
Installed power:
Inspection:
Report date:
Report type: Thermal drone report

-Available in Latvian language-

Inspection map



All detected issue locations in this inspection · Critical: red · High: orange · Medium: yellow · Low: blue

Summary (8 issues)

Priority	Count
Medium	8

Code	Title	Category	Priority	Status
4ccedc	Unknown anomaly	Unknown anomaly	Medium	Detected
6bfe26	Unknown anomaly	Unknown anomaly	Medium	Detected
e92dd5	Unknown anomaly	Unknown anomaly	Medium	Detected
85d640	Hot spot	Hot spot	Medium	Detected
6657d9	Hot spot	Hot spot	Medium	Detected
a0d8fb	Hot spot	Hot spot	Medium	Detected
a102a8	Hot spot	Hot spot	Medium	Detected
f32f04	Hot spot	Hot spot	Medium	Detected

4ccedc — Unknown anomaly

Category: Unknown anomaly

Priority: Medium

Status: Detected




Thermal drone image


Locator

Coordinates: demo


[Open Google Maps: demo](#)



Adjacent frames in sequence - the middle one (highlighted) is the image with the detected issue



Inspection overview - issue highlighted



Zoomed 50%

Recommended action

Perform a visual inspection and electrical measurements on site; determine the cause after diagnostics.

85d640 — Hot spot

Category: Hot spot

Priority: Medium

Status: Detected




Thermal drone image


Locator

Coordinates: demo


[Open Google Maps: demo](#)



Adjacent frames in sequence - the middle one (highlighted) is the image with the detected issue



Inspection overview - issue highlighted



Zoomed 50%

Recommended action

Inspect the module on site and take electrical measurements; replace the module if damage is confirmed.